

Part 573 Safety Recall Report

15V-752

Manufacturer Name : Newmar Corporation**Submission Date :** MAY 06, 2016**NHTSA Recall No. :** 15V-752**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 465

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2004-2007 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the Engine cooling fans may separate from the fan drive. If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured. The engine cooling fan may separate without warning. Correction: The fan drive for the engine cooling fan will be replaced at no charge.

Production Dates : MAR 24, 2003 - MAR 07, 2007

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2007-2008 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the Engine cooling fans may separate from the fan drive. If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured. The engine cooling fan may separate without warning. Correction: The fan drive for the engine cooling fan will be replaced at no charge.

Production Dates : JAN 19, 2006 - FEB 27, 2007

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2005-2007 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the Engine cooling fans may separate from the fan drive. If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured. The engine cooling fan may separate without warning. Correction: The fan drive for the engine cooling fan will be replaced at no charge.

Production Dates : MAY 30, 2005 - OCT 23, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the Engine cooling fans may separate from the fan drive. If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured. The engine cooling fan may separate without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes, the Engine cooling fans may separate from the fan drive. If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured. The engine cooling fan may separate without warning.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Motors, Inc.

Address : NR

NR

Country : United States

Chronology :

11/02/2015; Newmar Corporation received notification of a potential equipment defect relating to motor vehicle safety that may exist in specific engine cooling fans identified as potentially defective by Spartan Motors, Inc.

11/09/2015 Newmar sent Notice of Defect to NHTSA

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 08, 2016 - NR

Planned Owner Notification Date : JAN 08, 2016 - NR

* NR - Not Reported