

Part 573 Safety Recall Report**15V-772****Manufacturer Name :** Kingmor Supply, Inc.**Submission Date :** MAY 03, 2016**NHTSA Recall No. :** 15V-772**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Kingmor Supply, Inc.

Address : 6187 South Valley Pike
Mt. Crawford VA 22841

Company phone : 800-782-4474

Population :

Number of potentially involved : 240

Estimated percentage with defect : 95

Vehicle Information :

Vehicle : 2005-2014 IC CE

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : WHEELCHAIR LIFT INSTALLED ON NEW BUSES MAY BE AFFECTED UNDER THIS
RICON SAFETY RECALL #15E-068

Production Dates : SEP 01, 2005 - NOV 16, 2015

VIN (Vehicle Identification Number) Range

Begin : 4DRBUAFL96A258018

End : 4DRBUSKL4FB061439

 Not sequential VINs**Description of Defect :**

Description of the Defect : Ricon DOT Public Use, "S" 2000, 5000, 5500 Series lifts manufactured after January 1, 2006, equipped with platforms measuring 32"x51" and 34"x54"

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which if left unchecked can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. In the event the aforementioned crack occurs on both sides of the platform and is allowed to propagate to the point of material separation on both sides it is possible for the lift platform to lean against the vehicle door(s) and fall out of the vehicle when the door(s) is (are) opened putting the lift operator at risk.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

By letter dated October 19, 2015, Ricon Corporation provided a Safety Recall Notice OEM/Dealer 15E-068. November 16, 2015 Part 573 Defect and Noncompliance Report was submitted. December 14, 2015 NHTSA notification and complete mailing to customers.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported