

# Part 573 Safety Recall Report

# 15V-772

**Manufacturer Name :** Kingmor Supply, Inc.

**Submission Date :** MAY 17, 2016

**NHTSA Recall No. :** 15V-772

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** Kingmor Supply, Inc.  
**Address :** 6187 South Valley Pike  
 Mt. Crawford VA 22841  
**Company phone :** 800-782-4474

## Population :

**Number of potentially involved :** 271  
**Estimated percentage with defect :** 95 %

## Vehicle Information :

**Vehicle 1 :** 2005-2017 IC CE

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :** OTHER

**Power Train :** DIESEL

**Descriptive Information :** WHEELCHAIR LIFT INSTALLED ON NEW BUSES BY BE AFFECTED UNDER THIS RICON SAFETY RECALL #15E-068

**Production Dates :** SEP 01, 2005 - MAY 01, 2017

**VIN Range 1 : Begin :** 4DRBUAFL96A258018 **End :** 4DRBUC8N4HB651920  Not sequential

**Vehicle 2 :** 2005-2017 IC CE

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :** OTHER

**Power Train :** DIESEL

**Descriptive Information :** WHEELCHAIR LIFT INSTALLED ON NEW BUSES MAY BE AFFECTED UNDER RICON SAFETY RECALL #15E-068

**Production Dates :** SEP 01, 2005 - MAY 01, 2016

**VIN Range 1 : Begin :** 4drbuaf196a258018 **End :** 4drbuc8n4hb651920  Not sequential

## Description of Defect :

**Description of the Defect :** Ricon DOT Public Use, "S" 2000, 5000, 5500 Series lifts manufactured after January 1, 2006, equipped with platforms measuring 32"x51" and 34"x54"

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which if left unchecked can

propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. In the event the aforementioned crack occurs on both sides of the platform and is allowed to propagate to the point of material separation on both sides it is possible for the lift platform to lean against the vehicle door(s) and fall out of the vehicle when the door(s) is (are) opened putting the lift operator at risk.

Description of the Cause : NR

Identification of Any Warning  
that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : RICON CORPORATION

Address : 1135 AVIATION PLACE  
SAN FERNANDO CALIFORNIA 91340

Country : United States

## Chronology :

By letter dated October 19, 2015, Ricon Corporation provided a Safety Recall Notice OEM/Dealer 15E-068. November 16, 2015 Part 573 Defect and Noncompliance Report was submitted. December 14, 2015 NHTSA notification and complete mailing to customers.

## Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs  
from Recalled Component : NR

Identify How/When Recall Condition  
was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported