

Part 573 Safety Recall Report**15V-797****Manufacturer Name :** Newmar Corporation**Submission Date :** NOV 09,2015**NHTSA Recall No. :** 15V-797**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 10

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, manufactured by Newmar Corporation, a window having egress glass may not have been installed at the driver's side dinette table window. Not having an egress window on the opposite side of the entry door is a critical safety issue. An egress window is required per code for a second way to escape the vehicle if an accident/crash occurs. Correction: Newmar Dealers will inspect the window at the dinette table and add an egress window if needed.

Production Dates : MAR 09, 2015 - SEP 14, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : On certain motorhomes, manufactured by Newmar Corporation, a window having egress glass may not have been installed at the driver's side dinette table window. Not having an egress window on the opposite side of the entry door is a critical safety issue.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Not having an egress window on the opposite side of the entry door is a critical safety issue. An egress window is required per code for a second way to escape the vehicle if an accident/crash occurs.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Newmar Dealers will inspect the window at the dinette table and add an egress window if needed.

How Remedy Component Differs from Recalled Component : Not having egress glass in the window.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 08, 2016 - NR

Planned Owner Notification Date : JAN 08, 2016 - NR

* NR - Not Reported