

**Part 573 Safety Recall Report****15V-799****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** FEB 23, 2016**NHTSA Recall No. :** 15V-799**Manufacturer Recall No. :** R64**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 16,106

Estimated percentage with defect : 1

**Vehicle Information :**

Vehicle : 2015-2015 Ram ProMaster

Vehicle Type :

Body Style : VAN

Power Train : NR

Descriptive Information : Some 2015 MY Ram ProMaster ("VF") vehicles.

Production Dates : OCT 01, 2014 - JUN 17, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Some vehicles may experience an intermittent loss of electrical contact inside the ignition switch.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An intermittent loss of contact can result in a loss of motive power and/or a partial or complete drop-out of the following safety systems: Airbags, Anti-Lock Brakes, Electronic Stability Control and/or Instrument Panel Cluster.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : ZF TRW

Address : Via Miraflores 20

Nichelino FOREIGN STATES 10042

Country : Italy

**Chronology :**

Please see the attached supplement information titled "FCA US LLC Chronology - VF Ignition Switch - 11242015.pdf".

**Description of Remedy :**

Description of Remedy Program : FCA will conduct a voluntary safety recall on all affected vehicles to replace the ignition switch contact holder block.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : \*\* 2016 02 11 Final Dealer Notification - February 26  
Final Owner Notification - March 4

2016 01 05 - Planned interim dealer notification January 5, 2016. Planned interim owner notification January 8, 2016.

FCA US will provide a dealer notification and owner notification schedule once established.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported