

Part 573 Safety Recall Report**15V-797****Manufacturer Name :** Columbia Northwest, Inc.**Submission Date :** NOV 23,2015**NHTSA Recall No. :** 15V-797**Manufacturer Recall No. :** 15E-087**Manufacturer Information :**

Manufacturer Name : Columbia Northwest, Inc.
 Address : 1297 Kecksburg Road
 PO Box 131 Mount Pleasant PA 15666
 Company phone : 724-423-7440

Population :

Number of potentially involved : 46
 Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2013-2014 Somerset E1 and Santa Fe

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The vehicles covered by this report are recreation vehicles that were equipped with certain models of Atwood On Demand Water Heaters (ODWH) between 1-2-12 and 8-13-15.

Production Dates : NOV 01, 2012 - JAN 31, 2013

VIN (Vehicle Identification Number) Range

Begin : 1C9SS1412DA237109	End : 1C9SS1419DA237141	<input checked="" type="checkbox"/> Not sequential VINs
Begin : 1C9SS1419DA237110	End : 1C9SS1418DA237129	<input type="checkbox"/> Not sequential VINs
Begin : 1C9SS1411EA237006	End : 1C9SS1419EA237027	<input type="checkbox"/> Not sequential VINs
Begin : 1C9SS1412EA237001	End : 1C9SS141XEA237036	<input type="checkbox"/> Not sequential VINs

Description of Defect :

Description of the Defect : Atwood has found that the water flow adjustment feature on their models OD50, OD50CW, and OD45 the On Demand Water Heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3 gal/ minute or less.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : If this adjustment setting is allowed to drift to, or has been set at, .3 gal/ minute or less, the condition of concern can occur and can lead to a scald injury to the user.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Atwood Mobile Products

Address : 1120 N. Main Street
Elkhart INDIANA 46514

Country : United States

Chronology :

Atwood advised Columbia Northwest, Inc. of its defect determination via email dated 11/10/15. Columbia Northwest is not aware of any scald injuries in its vehicles that appear to be related to this defect.

Description of Remedy :

Description of Remedy Program : Atwood has arranged to conduct a recall to remedy the potential defect in Columbia Northwest, Inc. vehicles at no charge to the vehicle owners. See Recall 15E-087. Pursuant to 49CFR573.6(c)(8)(i) and 573.13, owners will be advised that Atwood will reimburse them if they have incurred costs to obtain a remedy for an ODWH containing such a defect prior to their receipt of the notification.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Columbia Northwest discontinued the use of the ODWH back in January 31, 2104.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 30, 2015 - DEC 16, 2015

Planned Owner Notification Date : NR - NR

* NR - Not Reported