

Part 573 Safety Recall Report**15V-819****Manufacturer Name :** Tiny Idahomes LLC**Submission Date :** DEC 04, 2015**NHTSA Recall No. :** 15V-819**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Tiny Idahomes LLC

Address : 315 s kings rd

Nampa ID 83687

Company phone : 2084680576

Population :

Number of potentially involved : 13

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2016 Tiny Idahomes Clear Creek

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : 18'-28' LONG RECREATIONAL TRAVEL TRAILERS

Production Dates : MAY 01, 2014 - DEC 01, 2015

VIN (Vehicle Identification Number) Range

Begin : 4T9U1KA24FN168111

End : 4T9u1ka27fn168118

 Not sequential VINs

Begin : 4t9bk2026fn168116

End : 4t9bk2622gn168123

 Not sequential VINs

Vehicle : 2014-2016 Tiny Idahomes Cascade

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : 18'-28' long pull behind travel trailer with regular loft

Production Dates : MAY 01, 2014 - DEC 01, 2015

VIN (Vehicle Identification Number) Range

Begin : 4T9U1KA2XFN168114

End : 4T9BK2026FN168116

 Not sequential VINs

Vehicle : 2015-2016 Tiny Idahomes F34MKMB3SL

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : One 34' gooseneck with 3 slide outs

Production Dates : MAY 01, 2015 - DEC 01, 2015

VIN (Vehicle Identification Number) Range

Begin :

End :

 Not sequential VINs**Description of Defect :**

Description of the Defect : Atwood Mobile Products has decided that the "defect" which relates to motor vehicle safety exists in a population of On Demand Water Heaters that it manufactured between 1/2/2012 thru 8/13/15 for installation in recreational vehicles

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : Atwood has found that the water flow adjustment feature on their models OD50, OD50CW and OD45 the on demand water heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3 gal/minute or less. If this adjustment setting is allowed to drift to, or has been set at .3 gal/ minute or less, the condition of concern can occur or can lead to a SCALD INJURY to the user. Atwood will offer to provide owners of all covered ODWH a rework for potential defect at no charge for parts or labor

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Atwood Mobile Products

Address : 1120 N Main Street

PO Box 1627 Elkhart INDIANA 46515

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported