

Part 573 Safety Recall Report**15V-829****Manufacturer Name :** Newmar Corporation**Submission Date :** DEC 08, 2015**NHTSA Recall No. :** 15V-829**Manufacturer Recall No. :** 15V 633**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 1,920

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 1997-2005 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning.

Production Dates : JAN 05, 1997 - MAY 26, 2005

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 1997-2005 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning.

Correction: The steering gear mounting bracket will need to be inspected, If cracks are found a new steering gear mounting bracket will be supplied at no charge.

Production Dates : JAN 05, 1997 - MAY 26, 2005

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 1998-1999 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning. Correction: The steering gear mounting bracket will need to be inspected, If cracks are found a new steering gear mounting bracket will be supplied at no charge.

Production Dates : JAN 05, 1997 - MAY 26, 2005

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2004-2004 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning. Correction: The steering gear mounting bracket will need to be inspected, If cracks are found a new steering gear mounting bracket will be supplied at no charge.

Production Dates : JAN 05, 1997 - MAY 26, 2005

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 1997-1998 Newmar Kountry Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning. Correction: The steering gear mounting bracket will need to be inspected, If cracks are found a new steering gear mounting bracket will be supplied at no charge.

Production Dates : JAN 05, 1997 - MAY 26, 2005

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Certain motorhomes may have a steering gear mounting bracket that could crack. If the steering gear mounting bracket cracks and breaks, it could result in a loss of steering which may increase the risk of a crash. This could occur without warning.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Correction: The steering gear mounting bracket will need to be inspected, If cracks are found a new steering gear mounting bracket will be supplied at no charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : FEB 05, 2016 - NR

Planned Owner Notification Date : FEB 05, 2016 - NR

* NR - Not Reported