

Part 573 Safety Recall Report**15V-839****Manufacturer Name :** Altec Industries Inc.**Submission Date :** DEC 11, 2015**NHTSA Recall No. :** 15V-839**Manufacturer Recall No. :** CSN 627**Manufacturer Information :**

Manufacturer Name : Altec Industries Inc.

Address : 210 Inverness Center Drive
Birmingham AL 35242

Company phone : 205-991-7733

Population :

Number of potentially involved : 8

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2013-2014 Manitex/PM Crane PM 3852 Series

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Knuckle Boom Crane

Production Dates : JAN 01, 2013 - DEC 31, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Cracks in outrigger weldments

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The outriggers could fail increasing the risk of death of serious injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : Inspection of the unit prior to use can identify cracks that develop

Supplier Identification :**Component Manufacturer**

Name : Manitex

Address : 3000 South Austin Avenue
Georgetown TEXAS 78626

Country : United States

Chronology :

Altec was notified by Manitex in late November of actions required to be taken on cranes manufactured by PM Cranes, a subsidiary of Manitex. Altec purchased from Manitex/PM and mounted on a motor vehicle chassis 8 of the effected cranes. Based upon discussions with Manitex, Altec determined that the Manitex document met the requirements for Altec to report this as a safety related defect to NHTSA. Altec will notify the affected customers of the units Altec installed of the inspection and repair requirements as published by Manitex.

Description of Remedy :

Description of Remedy Program : Altec will issue CSN 627 with the Manitex provided information to the 8 customers of Altec installed affected products: 1.) requiring an inspection of the outrigger box and repair of any cracks, 2.) installation of reinforcing collars.

How Remedy Component Differs from Recalled Component : Unknown. See Manitex/PM Notice

Identify How/When Recall Condition was Corrected in Production : Unknown. See Manitex/PM Notice

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : DEC 28, 2015 - DEC 30, 2015

Planned Owner Notification Date : NR - NR

* NR - Not Reported