

**Part 573 Safety Recall Report****15V-848**

**Manufacturer Name :** Jayco, Inc.  
**Submission Date :** FEB 04, 2016  
**NHTSA Recall No. :** 15V-848  
**Manufacturer Recall No. :** 9903273

**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.  
 Address : 903 South Main Street  
 PO Box 460 Middlebury IN 46540  
 Company phone : 800-283-8267

**Population :**

Number of potentially involved : 67  
 Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2016-2016 Class A Motor Home Alante 31L  
 Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES  
 Body Style :  
 Power Train : NR  
 Descriptive Information : G1AL0051-0119  
 Production Dates : NOV 03, 2015 - NOV 23, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : the seat belt for the rear and forward facing dinette seats in the Class A motor home does not have the proper backer plate to anchor the seat belt bracket.

FMVSS 1 : 210 - Seat belt assembly anchorages

FMVSS 2 : NR

Description of the Safety Risk : Improper anchoring may allow the seat belt to loosen / pull out and not restrain passenger if involved in accident which could lead to personal injury or death.

Description of the Cause : Production error

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

12-15-15 during routine testing on the Alante production line, it was discovered that the seat belts for the forward and rear facing dinette seats ( not the driver / passenger seats ) did not have the proper backer plate for the seat belt bracket. - IMMEDIATELY all Alante motor homes were placed on HOLD from shipping and then inspected.. Issue was found throughout -

**Description of Remedy :**

Description of Remedy Program : the correct backer plate will be installed with new bolts and fasteners and torque 35ft lbs at no charge to current owner - on all on site units and Jayco Dealers were perform the remedy for units in the field.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : the backer plate was secured and placed on units in production and ALL units still on site.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : FEB 10, 2016 - FEB 10, 2016

Planned Owner Notification Date : FEB 10, 2016 - FEB 10, 2016

\* NR - Not Reported