OMB Control No.: 2127-0004

Part 573 Safety Recall Report

15V-878

Manufacturer Name : Chrysler (FCA US LLC)

Submission Date: FEB 23, 2016 NHTSA Recall No.: 15V-878 Manufacturer Recall No.: R68



Manufacturer Information:

Manufacturer Name: Chrysler (FCA US LLC)

Address: 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone: 1-800-853-1403

Population:

Number of potentially involved: 60,140 Estimated percentage with defect: 1

Vehicle Information:

Vehicle: 2015-2015 Jeep Patriot

Vehicle Type : Body Style : SUV Power Train : NR

Descriptive Information: Certain 2015 MY Jeep Patriot vehicles.

Production Dates : JAN 01, 2015 - MAY 11, 2015

VIN (Vehicle Identification Number) Range

Vehicle: 2015-2015 Jeep Compass

Vehicle Type : Body Style : SUV Power Train : NR

Descriptive Information: Certain MY 2015 Jeep Compass vehicles.

Production Dates : JAN 01, 2015 - MAY 11, 2015

VIN (Vehicle Identification Number) Range

Description of Defect:

Description of the Defect: Some Jeep Compass and Jeep Patriot ("MK") vehicles may have been built with an

incorrectly placed power steering hose retention clamp, which could result in a detachment of the low pressure return hose, causing a large volume power steering

fluid leak.,

FMVSS 1:NR

FMVSS 2:NR

Description of the Safety Risk: This defect may, in certain rare circumstances, result in a vehicle fire.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name : NR Address : NR

NR

Country: NR

Chronology:

Please see the attached supplemental information titled "FCA US LLC Chronology – MK Steering – 12222015. pdf".

Description of Remedy:

Description of Remedy Program : Conduct a voluntary safety recall, on all affected vehicles to inspect the

return power steering hose for proper placement of the hose clamp, and

reposition the hose clamp as needed.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule: ** 2016 01 14 - Dealer instruction target date is 2016 01 29 and final owner

letter target is 2016 02 05.

FCA US will provide a dealer notification and owner notification schedule once

established

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

| Part 573 Safety Recall Report | 15V-878 | Page 3 |
|---------------------------------------|--|--------|
| | | |
| * NR - Not Reported | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| The information contained in this rep | port was submitted pursuant to 49 CFR §573 | |