

VOLKSWAGEN DEALERSHIP COMMUNICATION

Date: March 16, 2015

To: Dealer Principal, Sales Manager, Service Manager, Parts Manager and Warranty Administrator

Subject: Repair Instructions for Safety Recall 24BK – USA Only Fuel Injection System Leak 2012 MY Volkswagen Touareg Hybrid

IMPORTANT NOTICE TO DEALERS - FOR IMMEDIATE DISTRIBUTION Repair Instructions for Safety Recall 24BK

On March 17, 2015, repair instructions will be available for Safety Recall 24BK. Customer notification will also begin on this date.

Important Reminder on Vehicles Affected by Safety and Compliance Recalls

By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal/Canadian Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

If you have any questions or require additional assistance, please contact Warranty. As always, any press inquiries should be directed to Volkswagen Public Relations.

Volkswagen Customer Protection

Attachment: Revised Campaign Data Sheet (1)



CAMPAIGN DATA SHEET - REVISED

CAMPAIGN TYPE		Safety Recall
SAGA CODE		24BK
MARKET(S)		United States Only
AFFECTED VEHICLES		2012 MY Touareg Hybrid
ТОРІС		Fuel Injection System Leak
PROBLEM DESCRIPTION		Due to a combination of production tolerance issues and vehicle vibration during dynamic driving, it is possible that, in rare cases, a fuel leak may occur in the vehicle's fuel injection system. Leaking fuel, in the presence of an ignition source, may result in a fire.
		Additionally, some vehicles may benefit from having the thermostat updated. Repairs to this component are not related to the safety recall, but can easily be performed at the same time as the recall repair.
CORRECTIVE ACTION		To correct the safety defect, dealers will replace both fuel rails and the fuel injector seals.
		Additionally, some vehicles may also have the thermostat updated. This work is not related to the safety recall, but can easily be performed at the same time as the recall repair.
CUSTOMER NOTIFICATION DATE		March 17, 2015
ELSA VISIBILITY DATE		March 17, 2015
VIM VISIBILITY DATE		March 17, 2015
	TOTAL AFFECTED	USA : 201
VEHICLE COUNT	DEALER INVENTORY	USA : 0
	CPO INVENTORY	USA: 3
APPROXIMATE REPAIR TIME		Up to 460 TU
PARTS REQUIRED		SEE CAMPAIGN WORK PROCEDURE
PARTS ALLOCATION		Due to the small number of vehicles affected by this recall, there will be no parts allocation. If you have exceeded your weekly Upper Order Limit, please submit your requests for additional parts via email to <u>upperorderlimits@vw.com</u> .
EXPIRATION DATE		NONE
ADDITIONAL INFORMATION		Important Reminder on Vehicles Affected by Safety and Compliance <u>Recalls :</u> By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal/Canadian Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

IMPORTANT! To ensure that ALL of your personnel are aware of this action before receiving questions from any customer, please share this information with ALL personnel who have campaign-related responsibilities, including service writers, technicians, parts employees, warranty administrators, etc. See the campaign circular on Elsa for the most current repair information. Refer to the campaign circular for complete repair and claiming instructions.