



This Service Information bulletin supersedes SI M71 01 15 dated January 2015.

Changes to this bulletin are identified by a black bar.

SUBJECT

Delivery Stop Update: Regulatory Compliance Issue

MODEL

F56 (Cooper Hardtop 2-door)

SITUATION

BMW AG has decided to conduct a voluntary non-compliance Recall to replace both the tire and VIN label on certain Model Year 2014-2015 MINI Hardtop 2-door (only Cooper, excluding Cooper S) vehicles produced from December 2013 through December 2014. The vehicle capacity weight on the tire label and the GVWR (Gross Vehicle Weight Rating) on the VIN label are incorrect. Affected vehicles will be updated with labels indicating the correct values.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

This bulletin will be updated with instructions and warranty information when information becomes available. Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Vehicle Inquiry or ISPA Light with the description:

- Defect Code 0071160200, Delivery Stop, Potential Regulatory Compliance Issue, see SI M71 01 15.