



SUBJECT

Delivery Stop: Potential Regulatory Compliance Issue

MODEL

F56 (Cooper 2-door Hardtop)

SITUATION

A Delivery Stop has been issued on certain F56 (Cooper only) vehicles produced from December 2013 through December 2014, due to a potential regulatory compliance issue.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

This bulletin will be updated with instructions and warranty information when information becomes available. Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Vehicle Inquiry or ISPA Light with the description:

- Defect Code 0071160200, Delivery Stop, Potential Regulatory Compliance Issue, see SI M71 01 15.