

<b>Reference</b>	SSM72585
<b>Models</b>	XK / X150
<b>Title</b>	Urgent Action Required for Recall Action J049 - Parking Light Illumination
<b>Category</b>	Diagnostic Software Hardware
<b>Last modified</b>	09-Jan-2016 00:00:00
<b>Symptom</b>	000101 Diagnostic Concerns
<b>Content</b>	<p><b><u>Issue:</u></b></p> <p>When configuring the Central junction box (body control module) as existing using the JLR VCI for <b>J049</b>, the application may fail with an AOD block checksum error. This error will leave the Central junction box (body control module) in a non communicative state.</p> <p><b><u>Cause:</u></b></p> <p>The root cause of the failure is currently being investigated as a matter of urgency.</p> <p><b><u>Action:</u></b></p> <p>When you update the Central junction box (body control module) you <b>MUST</b> use one of the devices listed below:</p> <ul style="list-style-type: none"><li>• VCM</li><li>• I-View</li><li>• MongoosePro JLR</li><li>• DA Davina</li><li>• DA Dongle</li><li>• DA ST512</li></ul> <p><b>Do Not use the JLR VCI to configure the Central junction box (body control module)</b></p>