

IMPORTANT SAFETY RECALL NOTICE



565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

May 26, 2015

Re: Can-Am® Spyder® Roadster RT™ 2013 – Elevated Temperature in Engine Compartment

Dear Can-Am roadster Dealer,

This notice is being sent to you following the interim notice sent in February 2015, in accordance with the requirements of the National Traffic Motor Vehicle and Canada Motor Vehicle Safety Acts. BRP has decided that a defect which relates to motor vehicle safety exists on certain Can-Am roadster models and is conducting a safety recall. The remedy is now available.

What is the potential problem?

Under very hot ambient conditions and low speed riding, the temperature in the engine compartment may rise and thereby increase the risk of a skin burn or a vehicle fire.

Which models are involved?

Can-Am Spyder RT roadster, model year 2013.

What will BRP do?

BRP intends to repair involved vehicles, free of charge for the customer.

For dealers: BRP is publishing a Safety Campaign Bulletin describing procedures to install improved body panels and an upgraded fuel system kit.

For customers: BRP is sending to all known registered owners a Safety Recall letter. This letter urges owners to immediately contact their authorized BRP dealer in order to have their vehicle repaired.

Also, BRP is posting this notice on its dealer website BOSSWeb (www.bossweb.brp.com). Information for customers is posted on BRP's public website (www.can-am.brp.com).

What should you do?

- Do not sell or deliver any involved vehicle that you have in stock as federal law requires you to complete the recall service on these vehicles before retail delivery.
- Contact all of your customers who have purchased an affected Can-Am Spyder roadster. You must inform them about the foregoing and must request them to make an appointment to get their vehicle repaired.
- Follow all instructions provided in the attached Safety Campaign Bulletin.
- Inform any owner that cannot get his vehicle repaired immediately that, although BRP insist to get all involved vehicles repaired rapidly, they can keep using their vehicle while taking the following precautions in hot riding conditions (ambient temperature of approximately 30 C/85 F and more):
 - o Avoid idling or slow traffic riding for a long period of time.
 - o Avoid parking in an enclosed area immediately after a ride, let vehicle cool down first.
 - o Avoid prolonged direct contact with body panels; wear appropriate riding gear as stated in the Operator's Guide.

Ski-Doo
Lynx
Sea-Doo
Evinrude
Rotax
Can-Am

Please note that the National Traffic and Motor Vehicle Safety Act provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. Failure to repair within sixty (60) days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. The owner may be entitled to an identical or reasonable equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

If you have questions about this notice, please communicate with us:

- By submitting a **BOSSWeb case**. A service representative will communicate with you.
- OR**
- In USA and Canada: [1-800-366-6992](tel:1-800-366-6992)
Eastern time Monday to Friday from 10:00 AM to 5:00 PM

Thank you for your immediate attention to this matter.

Sincerely,
After-Sales Service Department