



# Service Information

Audio, Navigation, Monitors,  
Alarms, SRS

B65 04 15

Page 1 of 3

March 2015

Technical Service

---

## **SUBJECT**

### **Delivery Stop: Reprogram Advanced Crash Safety Module**

## **MODEL**

F33 (4 Series Convertible)

## **SITUATION**

A Delivery Stop has been issued on certain F33 vehicles produced from November 1, 2014 through February 27, 2015. These vehicles may be equipped with faulty airbag control unit software.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

This bulletin will be updated with instructions and warranty information when it becomes available. Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

- Defect Code 0065830200, Delivery Stop, Program Airbag Control Unit, see SI B65 04 15.