

GM CUSTOMER CARE AND AFTERSALES
DCS3604
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 26, 2015

Subject: 15176 - Noncompliance Recall
Sunroof Switch Compliance
Repair Completion Releases Only 2015 Malibu From
Stop Delivery

Models: 2013-2015 Chevrolet Malibu Equipped with Power-Operated
Roof Panel System (RPO CF5)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors is releasing Noncompliance Recall 15176 today. The total number of U.S. vehicles involved is **87,063**. Please see the attached bulletin for details.

This recall is being administered in phases. The first phase is the 2015 model year Chevrolet Malibu vehicles. The software calibration for these vehicles is currently available. The software calibration for the 2013-2014 model year Chevrolet Malibu vehicles will be available in the near future. Do not attempt to reprogram these vehicles with the 2015 software calibration. Dealers will be advised when the 2013-2014 software calibration is available.

Customer Letter Mailing

The customer letter mailing will begin in the near future.

Global Warranty Management (GWM)

The Investigate Vehicle History screen in the GWM system will be updated on March 27, 2015 for the 2015 model year Chevrolet Malibu vehicles. A list of involved 2015 model year Chevrolet Malibu vehicles in dealer inventory is attached to this message.

Campaign Initiation Detail Report (CIDR)

A CIDR for the 2015 model year Chevrolet Malibu vehicles will be available on March 31, 2015.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES