



Michael A. Berardi
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 25, 2015

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD Advance Notice - Safety Recall 15S10
Certain 2013-2015 Model Year Lincoln MKT Limo and Hearse Vehicles
Brake Booster Vacuum Pump Relay Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
MKT Limo and Hearse	2013-2015	Oakville	March 6, 2012 through March 10, 2015

Affected vehicles are identified in OASIS.

REASON FOR THIS SAFETY RECALL

In some of the affected vehicles, the brake booster vacuum pump relay may develop a short circuit internally. This condition may produce heat sufficient enough to produce smoke and/or a fire.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any of the affected vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers in May 2015 when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery

QUESTIONS

Special Service Support Center (Dealer Assistance Only)1-800-325-5621

Sincerely,

Michael A. Berardi