



This Service Information bulletin supersedes SI B16 03 15 dated June 2015.

## **SUBJECT**

### **Recall Campaign 15V-189: Replace Low-pressure Electric In-tank Fuel Pump**

## **MODEL**

F22 (2 Series Coupe)  
F30 (3 Series Sedan)  
F30 H (ActiveHybrid 3)  
F31 (3 Series Sports Wagon)  
F32 (4 Series Coupe)  
F33 (4 Series Convertible)  
F34 (3 Series Gran Turismo)  
F36 (4 Series Gran Coupe)

## **SITUATION**

BMW AG is conducting a voluntary Safety Recall involving the fuel pump on certain Model Year 2014 and 2015 2 Series, 3 Series and 4 Series vehicles.

Affected vehicles may be equipped with a fuel pump which can become inoperative due to improper plating of certain subcomponents within the fuel pump.

This bulletin will be updated with instructions and warranty information when it becomes available. Please contact your field representatives if you have any questions.

An interim letter has been mailed out to customers, informing them that their vehicle is affected by this Recall. However, at this time, we are not ready for the customer to visit the dealer for the repair.

For your reference, the interim letter and Q&A has been attached.