

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS3958  
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 11, 2016

Subject: 14574C – Safety Recall  
Engine Oil Leak on Exhaust Manifold  
Revised Warranty Transaction and Service Procedure

Models: 2004 Buick Regal  
2004 Chevrolet Impala  
2004 Chevrolet Monte Carlo  
2004 Pontiac Grand Prix  
Equipped with 3.8L V6 engine (RPO L26, L32, L36 or L67)

To: All General Motors Dealers

The Warranty Transaction section and Service Procedure in this bulletin has been revised to provide service repair tips that may reduce the amount of time and effort required to perform the repair. In addition, beauty cover removal, retention, and disposal information is provided. Please discard all copies of bulletin 14574B.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS