



Mitsubishi Motors North America, Inc. PARTS BULLETIN

| | |
|---|---|
| SUBJECT: FRONT BLOWER MOTOR - SAFETY RECALL CAMPAIGN | No: 55-XX-01-15 |
| | Date: JUNE 2015 |
| | Model: LANCER; LANCER RALLIART; LANCER SPORTBACK; LANCER SPORTBACK RALLIART; LANCER EVOLUTION; OUTLANDER; OUTLANDER SPORT/RVR |

PURPOSE:

Due to a manufacturer error, the shaft and bearing inside the front blower motor on affected vehicles may have been improperly centered. If use continues under this condition, the shaft and bearing could ultimately seize resulting in total loss of blower performance.

Please reference SAFETY RECALL BULLETIN SR-15-003 for the procedures on how to inspect and replace with a countermeasure unit if necessary on affected vehicles built within a certain production period.

AFFECTED VEHICLES:

- Certain 2009 - 2011 Lancer vehicles built March 16, 2009 to March 30, 2011
- Certain 2009 – 2011 Lancer Ralliarts built June 17, 2009 to December 1, 2010
- Certain 2010 - 2011 Lancer Sportback vehicles built June 17, 2009 to December 1, 2010
- Certain 2010 – 2011 Lancer Sportback Ralliarts built June 17, 2009 to November 23, 2010
- Certain 2010 - 2011 Lancer Evolution vehicles built July 14, 2009 to January 7, 2011
- Certain 2009 - 2011 Outlander vehicles built February 10, 2009 to June 22, 2011
- Certain 2011 Outlander Sport/RVRs vehicles built August 26, 2010 to November 19, 2010

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or non-compliance is remedied.

PARTS INFORMATION

| PART NUMBER | DESCRIPTION | VEHICLE APPLICABILITY | Qty |
|-------------|--------------------------------|--|-----|
| 7802A217 | BLOWER MOTOR | 2009 – 2011 Lancer 2009 – 2011 Lancer Ralliart 2010 – 2011 Lancer Sportback with F.A.S.T - key 2010 – 2011 Lancer Sportback Ralliart with F.A.S.T - key 2009 – 2011 Outlander with F.A.S.T - key | 1 |
| 7802A218 | BLOWER MOTOR with NOISE FILTER | 2010 – 2011 Lancer Sportback without F.A.S.T – key 2010 – 2011 Lancer Sportback Ralliart without F.A.S.T – key 2010 – 2011 Lancer Evolution 2009 – 2011 Outlander without F.A.S.T – key 2011 Outlander Sport/RVR | 1 |
| 7802A006 | POWER TRANSISTOR | ALL – ONLY IF the Blower Motor cannot achieve “MAX” performance will this part be replaced. | 1* |

*if required



Mitsubishi Motors North America, Inc.
PARTS BULLETIN

SUBJECT:

**FRONT BLOWER MOTOR -
SAFETY RECALL CAMPAIGN**

No: 55-XX-01-15

Date: JUNE 2015

Model:

LANCER; LANCER RALLIART; LANCER
SPORTBACK; LANCER SPORTBACK
RALLIART; LANCER EVOLUTION;
OUTLANDER; OUTLANDER SPORT/RVR

PARTS ORDERING AND ALLOCATION INFORMATION:

Part shipments will be processed via the 'R' order type and will be shipped along with your scheduled stock order beginning Wednesday June 10, 2015. Force allocation orders should be received at your dealership on or before June 17, 2015. Additional orders may be placed via the MDL if necessary.

- NOT all vehicles affected in the recall will require the Power Transistor.
 - Only affected vehicles that cannot achieve "MAX" power will have the Power Transistor replaced.
- Most dealers will receive a portion of parts to service VINs for their area.

Contact your local Zone Representative, District Parts and Service Manager, or Facing PDC for questions or comments.

