# **SAFETY RECALL**



## **CAMPAIGN BULLETIN**

## Takata Passenger Airbag Inflator Voluntary Safety Recall Campaign

Reference: R1303/R1406

Date: June 16, 2017

Attention: Retailer Principal, Sales, Parts and Service Managers

#### REVISED June 16, 2017

- Campaign ID R1303/R1406 is no longer active.
- Vehicles remedied under this campaign require no further action at this time. Infiniti will notify those owners should additional action be necessary.
- Any VINs subject to R1303 that were not remedied are now identified by **R1713** and refer to the following campaign repair bulletins:
  - o ITB17-021 -2002-2003 QX4 (JR50)
  - o ITB17-022 2003-2005 FX35/45 (S50)
  - o ITB17-038 2001 I30 (CA33)/2002-2004 I35 (CA33)

Please discard earlier versions of this bulletin and refer to the R1713 bulletin for additional details.

#### \*\*\*\*\* Part Return Information \*\*\*\*\*

Infiniti is allowing retailers to return any of the following parts to facing PDCs (using a "G" code) to be scrapped until August 16, 2017.

- K8561-7994D
- K8E61-7994D
- KH5FA-7993D
- K85FA-7994D

Parts returned by August 16, 2017 will not affect a retailer's parts accrual credit. Parts returned after this date may be subject to using a retailers parts return accrual.

#### \*\*\*\*\*Claim Information \*\*\*\*\*

Retailers should submit any open claims for repairs performed under this campaign ID (R1303) by June 30, 2017.

#### **CLAIMS INFORMATION**

Submit a "CM" line claim using the following claims coding:

FΧ

<u>1 /                                   </u>			
Campaign ("CM") I.D.	DESCRIPTION	OP CODE	FRT
R1303*	<b>FX</b> – Remove and replace front	R13030	
R1406*	passenger air bag inflator	R14061	1.1 hrs

<sup>\*</sup>Be sure to use the claims coding information that matches the open CM from Service Comm.  $\mathbf{OR}$ 

### 130/135

Campaign ("CM") I.D.	DESCRIPTION	OP CODE	FRT
R1303*	I30 or I35 – Remove and	R13031	
R1406*	replace front passenger air bag inflator	R14060	0.8 hrs

<sup>\*</sup>Be sure to use the claims coding information that matches the open CM from Service Comm.

## <u>OR</u>

### QX4

Campaign ("CM") I.D.	DESCRIPTION	OP CODE	FRT
R1303*	<b>QX4</b> - Remove and replace front	R13032	
R1406*	passenger air bag inflator	R14062	0.9 hrs

<sup>\*</sup>Be sure to use the claims coding information that matches the open CM from Service Comm.

### **EXPENSE CODE**

CODE	DESCRIPTION	MAXIMUM AMOUNT		
041	Shorting Pin (Insulation Displacement Connector for 22-18 gauge wire)	\$0.50		
502	Rental Expense	\$180		
Contact the Warranty claims call center 1-800-933-3712 Option 7, if additional expense is required.				