

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: June 15, 2015
TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers, and Parts Managers
RE: Raider Driver Side Frontal Air Bag Inflator Safety Recall – Notice To Stop Use - P/N CBRZP401AA
TIN NO. TIN-15-SR-007-A

.....

AFFECTED VEHICLES: Certain 2006 to 2009 Raiders

PURPOSE

Pursuant to a Defect Information Report that TK Holdings Inc. (Takata) submitted to the National Highway Traffic Safety Administration (NHTSA), Service Campaign SC-14-005REVII – Raider Driver Side Air Bag Inflator – Special Service Campaign – Revised, **has been (1) upgraded to a Safety Recall, and (2) will now include 2006 – 2009 Raiders** – the geographic scope remains national. All Raiders affected by the previous Special Service Campaign are affected by this new Safety Recall.

The replacement air bag kit (p/n CBRZP401AA) you have been using to perform the Special Service Campaign has been determined by Takata to be defective. As a result, **effective immediately, do not install p/n CBRZP401AA on any vehicles that have campaign C1415R open on the Warranty Superscreen. Installation of p/n CBRZP401AA into any vehicle is now illegal.**

A replacement inflator part sourced from a different supplier will be made available for order in the next few days. When this new inflator part becomes available, you will receive the new part number for this part along with instructions how to return any p/n CBRZP401AA currently in your inventory. Again, it is imperative that you discontinue installation of p/n CBRZP401AA on any vehicle.

Those vehicles that already received p/n CBRZP401AA under the Special Service Campaign, will be recalled again under the new Safety Recall in order to receive the new replacement inflator part sourced from a different supplier.

If campaign C1415R was performed on any vehicle prior to receipt of this notice, please enter the claim in the Warranty system by June 22, 2015 to be appropriately reimbursed. Repairs made after June 16, 2015 using p/n CBRZP401AA may not be eligible for reimbursement.

MMNA expects to provide the Recall Campaign Bulletin outlining the repair procedure on MEDIC and MDL in the next few days. An ATIN will be distributed once this recall campaign (SR-15-007) is officially launched. Using the new replacement inflator part, please perform this Safety Recall on affected vehicles that display campaign C1507R as open on the Warranty Superscreen.

In the event you receive any direct customer inquiries regarding this issue, please refer them to the MMNA Customer Relations Hotline at (888) 648-7820.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.