

[Next Unread Message](#)**View Message**

**Sent on** 05 28 2015 **Expires on** 08 25 2015  
**From** Acura Parts, Service & Technical Division, and Campaign Administration  
**Subject** Multi-Model Airbag Inflator Safety Recall-Campaign Update

DATE: May 28, 2015

TO: All Acura Parts & Service Managers and Personnel  
FROM: Acura Parts, Service & Technical Division, and Campaign Administration

RE: Multi-Model Airbag Inflator Safety Recall-**Campaign Update**

On Wednesday, May 27th, Acura notified NHTSA of the intent to launch one new airbag inflator safety recall for driver's airbag inflators.

**Details Related to Driver's Side**

The driver's side recall adds no new VINs to the overall population. All unfixed VINs will be moved from the following campaign ranges into a new campaign range with a new service bulletin:

09-033 - *Safety Recall: Driver's Airbag Inflator Can Be Over-Pressurized*  
10-026 - *Safety Recall: Replacement Driver's Airbag Inflator Can Be Over-Pressurized*  
14-029 - *Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity*

Acura is currently working to update the recall database to reflect this change, and expects to have the VINs migrated from the three old actions into a single recall by June 5, 2015. Until that time, affected VINs are already eligible for 09-033, 10-026, or 14-029, and should continue to be repaired under those service bulletins.

Vehicles that have been repaired with a replacement driver's airbag inflator on or after September 12, 2014 do not require further action, and will be omitted from this population.

**Client Notification**

Acura expects to notify clients affected by this recall beginning in early July, and completing by July 27, 2015.

As always, be sure to check VIN inquiry to determine if a particular VIN is eligible for any open recalls.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.