

[Next Unread Message](#)**View Message**

<b>Sent on</b>	04	04	2018	<b>Expires on</b>	04	13	2018
<b>From</b>	National Field Recall						
<b>Subject</b>	Airbag Inflator Mobile Repair Process-Claim Submission Requirements						

### Background

This Airbag Inflator Mobile Repair Claim Submission Process applies to specific Non-Alpha PG1-3 VINs affected by (Acura S/B 15-033 *Safety Recall: Driver's Airbag Inflator Can Be Over-Pressurized*) & (Acura S/B 15-049 *Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized*). This process is available for your Acura Dealer to request an additional 0.6 hours of labor for Dealer Technician assisted mobile repairs only. We appreciate your on-going support with this activity.

### Requirements

- **Zone Recall Manager Authorization** is required on all Airbag Inflator Mobile Repair Claims.

### Instructions

- The **Line item** on the RO should state "Airbag Inflator Mobile Repair" (this must be transferred to the customer contention description).
- A **Template ID** is required for each affected vehicle to receive an additional 0.6 hours of labor for the mobile repair and should **ONLY** be claimed by Dealers when Dealership personnel perform the work.
- **Note: Only 1 Mobile Repair Template is allowed per VIN.** If both Driver and Passenger side inflator repairs are performed to the same VIN, Dealers are only allowed to claim 1 mobile repair template. The opposite side should have a warranty claim submitted using the non-mobile repair template ID from the standard service bulletin.

[Click here](#) to view Acura's **Warranty Claim Information**.