



Michael A. Berardi
 Director
 Service Engineering Operations
 Ford Customer Service Division

Ford Motor Company
 P. O. Box 1904
 Dearborn, Michigan 48121

September 23, 2015

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: **DEMONSTRATION / DELIVERY HOLD - Compliance Recall 15C06 - Supplement #1**
 Certain 2015 Model Year Escape, Focus, and C-MAX
 Body Control Module Reprogramming

REF: **DEMONSTRATION / DELIVERY HOLD - Compliance Recall 15C06**
 Dated July 1, 2015

New! REASON FOR THIS SUPPLEMENT

Service procedure: To help reduce the potential for DTCs or other concerns after reprogramming, the IDS module reprogramming procedure for the body control module (BCM) has been updated. Dealers are to use IDS release 97.02 or higher to reprogram the BCM on affected vehicles. Vehicles that have already been serviced under 15C06 do not require additional repairs.

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Escape	2015	Louisville	April 1, 2014 through June 12, 2015
Focus	2015	Michigan	June 17, 2014 through June 12, 2015
C-MAX	2015	Michigan	April 22, 2014 through June 12, 2015

Affected vehicles are identified in OASIS and FSA VIN list.

REASON FOR THIS COMPLIANCE RECALL

In some of the affected vehicles, the engine may continue to run after turning the ignition key off (vehicles with standard ignition keys), or after pressing the Engine Start/Stop button (vehicles with push-button start and intelligent access keys). Affected vehicles can be operated without the key, which does not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) 114 – regarding Theft Protection and Rollaway Prevention.

New! SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this recall, dealers are to reprogram the body control module (BCM) using IDS release **97.02** or higher. This service must be performed on all affected vehicles at no charge to the vehicle owner.

OWNER NOTIFICATION MAILING SCHEDULE

Owner Letters are expected to be mailed the week of July 20, 2015. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Owner Notification Letter

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael A. Berardi".

Michael A. Berardi

DEMONSTRATION / DELIVERY HOLD - Compliance Recall 15C06 - *Supplement #1*

Certain 2015 Model Year Escape, Focus, and C-MAX
Body Control Module Reprogramming

OASIS ACTIVATED?

Yes, OASIS will be activated on July 1, 2015.

FSA VIN LIST ACTIVATED?

Yes, FSA VIN list will be available through <https://web.fsavinlists.dealerconnection.com> on July 1, 2015. Owner names and addresses will be available by August 3, 2015.

NOTE: Your FSA VIN list may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries.

Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

STOCK VEHICLES

Correct all affected units in your new vehicle inventory before delivery.

SOLD VEHICLES

- Owners of affected vehicles will be directed to dealers for repairs.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.

TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this recall.

ADDITIONAL LABOR TIME AND/OR PARTS

Contact the Special Service Support Center (SSSC) if you have any of the following:

- Damage that you believe was caused by the covered condition.
- A condition that requires additional labor and/or parts to complete the repair.
- Aftermarket equipment or non-Ford modifications to the vehicle which might prevent the repair of the covered condition.

Requests for approval after completion of the repair may not be granted. Ford Motor Company reserves the right to deny coverage for related damage in cases where the vehicle owner has not had this recall performed on a timely basis. Additional related damage parts are subject to random selection for return to the Ford Warranty Parts Analysis Center (WPAC).

OWNER REFUNDS

Refunds are not approved for this program.

DEMONSTRATION / DELIVERY HOLD - Compliance Recall 15C06 - *Supplement #1*

Certain 2015 Model Year Escape, Focus, and C-MAX
Body Control Module Reprogramming

RENTAL VEHICLES

The use of rental vehicles is not approved for this program.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using Direct Warranty Entry (DWE) or One Warranty Solution (OWS).
 - DWE: refer to ACESII manual for claims preparation and submission information.
 - OWS: when entering claims in DMS software, select claim type 31: Field Service Action. The FSA number (15C06) is the sub code.
- Additional labor and/or parts must be claimed as related damage on a repair line that is separate from the repair line on which the FSA is claimed. Additional labor and/or parts require prior approval from the SSSC via the SSSC Web Contact Site.

DEMONSTRATION / DELIVERY HOLD - Compliance Recall 15C06 - *Supplement #1*

Certain 2015 Model Year Escape, Focus, and C-MAX
Body Control Module Reprogramming

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Reprogram the BCM	15C06B	0.2 Hours

PARTS REQUIREMENTS / ORDERING INFORMATION

Parts are not required to complete this repair.