From:	July 15, 2015 Parts Logistics July 29, 2015	DCSnet Message Urgent	
Subject:	MINI Side Impact Performance Delivery Stop		

To: All MINI Parts and Service Managers

Re: MINI Side Impact Performance Delivery Stop

On Monday, July 13th a delivery stop was announced for MINI (F56) Side Impact Performance.

For more information, please reference MINI Service Information Bulletin M51 03 15 and M51 04 15. These Bulletins will be updated with the part number information by the end of the week.

To support the repair of these vehicles, we have entered orders as noted below:

Weld Hot Melt Applicator 83 19 2 409 988 1 to each dealer Weld Hot Melt Adhesive 83 19 2 409 987 1 to each dealer (box of 15 sticks, must be ordered in increments of 15; 1 stick more than sufficient for repairing 1 car)

To order the L-Pads (1 Left and 1 Right per each VIN) please do the following:

Email your VIN specific orders to <u>Specialpartsrequest@bmwna.com</u> (Last seven digits of VIN)

Include all affected inventory VINs at your dealership in the single email. Include your dealer ship to location, with contact information and delivery address

Please do not send VINs that are not included in the delivery stop. At this time we are only addressing those inventory vehicles which have a delivery stop. Any affected vehicles at the VDCs will be addressed prior to delivery.