

GM CUSTOMER CARE AND AFTERSALES
DCS3736
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 5, 2015

Subject: 15075 - Safety Recall
Side Impact Sensor (SIS) Wire Chafe at Window Regulator

Models: 2010 Chevrolet Cobalt

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

General Motors is releasing Safety Recall 15075 today. The total number of U.S. vehicles involved is approximately 59,474. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin in the near future.

Global Connect (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated August 6, 2015.

Campaign Initiation Detail Report (CIDR)

The CIDR will be available in the near future.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES