

*** * ADVANCE TECHNICAL INFORMATION NOTICE * ***

DATE: October 2, 2015
TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, General Managers, Service Managers, and Parts Managers
RE: Right Parking Brake Cable Interference with Fuel Tank - Safety Recall Campaign
ATIN NO. ATIN-15-SR-009-A

AFFECTED VEHICLES: Certain 2014 – 2015 Lancer Ralliart and Lancer Evolution

PURPOSE

A safety recall campaign will be released today for potential right parking brake cable interference with the fuel tank in certain 2014 - 2015 Lancer Ralliarts built February 3, 2014 to September 5, 2014, and certain 2014 – 2015 Lancer Evolutions built January 31, 2014 – September 5, 2014. This recall campaign will be conducted in the U.S. and Canada. The Recall Bulletin outlining the repair procedure will be available today on MEDIC and MDL.

Due to an improper installation of the right parking brake cable, the cable may have insufficient clearance with the fuel tank, causing abrasive contact between the two components. The coating on the fuel tank could deteriorate from this abrasive contact and potentially allow for rust formation. In the worst case scenario, a pin hole could develop and allow for fuel leakage.

Dealers are requested to replace the right parking brake cable and inspect the fuel tank. If the fuel tank's coating exhibits damage from abrasive contact with the right parking brake cable, the fuel tank will also be replaced.

Some dealers have been force allocated stock using a formula based on the proximity and percentage of applicable registered VINs by ZIP code. Parts shipments were processed via the 'R' order type and started shipping along with your scheduled stock order beginning Wednesday, September 30, 2015. Dealers may place additional orders via the MDL. Please refer to Parts Bulletin 35-XX-01-15 for additional information.

Notification letters will be sent to owners of affected vehicles, requesting they contact their local Authorized Mitsubishi dealership to schedule an appointment to have this recall performed.

Affected new vehicle inventory VINs can be reviewed on the Mitsubishi Dealer Link in the **Most Recent: Open Campaign List** available under the service section of "e-reports." Dealers must review the Warranty Superscreen to confirm if any vehicles in their new or used vehicle inventories are affected, and conduct this campaign prior to delivering them. When checking for applicability of this campaign (C1510W), please check for and complete any other open campaigns. Always get the customer's approval before completing a campaign on a customer owned vehicle.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Superscreen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.