

[Next Unread Message](#)**View Message**

Sent on 09 03 2015 **Expires on** 12 01 2015
From Campaign Administration
Subject Stop Sale/Safety Recall: 2015 Fit Plug Top Coil Noise Suppressor

DATE: September 3, 2015

TO: All Honda Sales, Service & Parts Managers and Personnel

FROM: Campaign Administration

RE: Stop Sale/Safety Recall: 2015 Fit Plug Top Coil Noise Suppressor

Yesterday, September 2, 2015, American Honda notified NHTSA of a **Safety Recall** for approximately 18,000 2015 Fit vehicles due to plug top coil noise suppressors that may fail. **Any new or used units** in dealer stock **must be repaired per service bulletin, 15-060: Safety Recall: Ignition Coils, prior to sale**. Refer to your eResponsibility report or VIN inquiry to determine which units in your inventory are affected. American Honda Motor Co. expects to begin customer notification in early October 2015.

Note: Affected vehicles should not be sold until the repair has been completed. Should an unrepaired vehicle result in any claim because of the required recall repair, the dealership will be solely responsible to the claimant, and will be required to defend and indemnify American Honda for any resulting claims.

Basic Problem

Design of the plug top coil noise suppressor is prone to damage due to damage caused by electrical arcing. Damaged coils may cause the illumination of dashboard warning lights, DTCs P0301-P0303 (engine misfire), and engine malfunction.

Campaign Information

Service bulletins 15-060, has been posted to the Service Information System as of September 3, 2015, and includes warranty, parts, and repair information related to the recall campaign.

Parts Information

Replacement coils are available to support this safety recall.

Warranty and Repair Information

Warranty and repair information is detailed in service bulletin 15-060.

Customer Notification

American Honda expects to complete initial customer notification by early October.

As always, please be sure to check VIN status inquiry to determine if a particular VIN is affected by this recall.

Click [here](#) for a copy of bulletin 15-060.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.