

**SUBJECT****Recall 15V-xxx: Passenger-Side Front Airbag****MODEL**

I01 (i3)

SITUATION

BMW AG is conducting a Voluntary Non-Compliance Recall including Delivery Stop involving the passenger-side front airbag in certain i3 (I01).

Due to a supplier error in the manufacturing process, internal components of the airbag inflator were not assembled as specified.

For your reference, a Q&A has been attached.

This bulletin will be updated with repair instructions, parts and warranty information when it becomes available.

Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

“A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. See Service Information Bulletin B65 18 15.”

ATTACHMENTS

View PDF attachment [Recall Notice B651815](#).

View PDF attachment [B651815 Q&A](#).

[Copyright ©2015 BMW of North America, Inc.]