



SI M65 11 15
Audio, Navigation, Monitors, Alarms, SRS M65 11
15 Technical Service

October 2015
Technical Service

SUBJECT

Recall 15V-xxx: Passenger-Side Front Airbag

MODEL

F56 (Hardtop 2-door)

F55 (Hardtop 4-door)

SITUATION

BMW AG is conducting a Voluntary Non-Compliance Recall including Delivery Stop involving the passenger-side front airbag in certain:

- Model Year 2014-2016 MINI Cooper and Cooper S Hardtop 2 Door (F56)
- Model Year 2015-2016 MINI Cooper and Cooper S Hardtop 4 Door (F55)
- Model Year 2015-2016 MINI John Cooper Works

Due to a supplier error in the manufacturing process, internal components of the airbag inflator were not assembled as specified.

For your reference, a Q&A has been attached.

This bulletin will be updated with repair instructions, parts and warranty information when it becomes available.

Please contact your field representatives if you have any questions.

Affected vehicles can be identified with a "Vehicle Comment" in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. See Service Information Bulletin M65 11 15."

ATTACHMENTS

View PDF attachment [M651115 Q&A](#).

View PDF attachment [Recall Notice M651115](#).

[Copyright ©2015 BMW of North America, Inc.]