

- [26-01-038H - Front Coil Spring Urethane Tube Installation \(Recall 133\) \(posted 06.12.26\).pdf](#)
[RC133 Dealer Notification \(Remedy\) - Urethane Spring Tubes Install \(posted 06.12.26\).pdf](#)

Hyundai Motor America (HMA) has re-launched Recall 133: Front Coil Spring Urethane Tube Installation.

It is being re-launched with the following revisions in the Technical Service Bulletin (TSB):

1. Revised sealant part number (page 2)
2. Revised NOTE 2 under the 'Warranty Information' section (page 3)
3. Additional minor notes to the service procedure (pages 4-12)

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

A. Recall Description:

On certain 2011 Elantra (MD) and Sonata (YF) vehicles, corrosion can build up at the front coil springs, resulting in a possible fracture near the base. A fractured spring can make contact with the tire, potentially resulting in a tire puncture and increasing the risk of a crash.

Technical Service Bulletin (TSB) 26-01-038H describes the procedure to install urethane tubes over the front coil springs to prevent a tire puncture.

B. Affected Vehicles:

VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine recall applicability.

- 2011MY Elantra (MD) produced 11/12/2010 – 03/31/2011
 - Built by Hyundai Motor Company ("HMC")
- 2011MY Sonata (YF) produced 12/11/2009 – 02/28/2010
 - Built by HMC

Area: Connecticut, Delaware, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, Wisconsin, and the District of Columbia

C. Campaign Document(s):

1, TSB 26-01-038H

- a. Available on HyundaiDealerUSA.com > Service > Service Programs > HMA Tech Info > Campaign

2. Dealer Notification

- a. Available on HyundaiDealerUSA.com > Service > Service Programs > HMA Tech Info > Service News

D. Action Required:

1. Confirm VIN eligibility for the recall via WebDCS.
2. **Follow TSB 26-01-038H** for the service procedure to install the front coil spring urethane tubes.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America