

MAZDA DEALER EMAIL



---

April 25, 2016

Attention: Mazda Service and Parts Managers

Subject: Update on Safety Recall 8715J - Ignition Switch May Overheat

Due to differences in early model year Protégé ignition switch design, the 8715J repair procedure and warranty information have been updated.

Please be sure to follow the updated instructions for 1995-1998 Protégé models.

Current repair and warranty information on recall 8715J are available on the Mazda Service Support System (MS3) website and on eMDCS via MXConnect.

Your understanding and support in carrying out this recall are greatly appreciated.

Mazda Technical Services

---

*ZOOM-ZOOM*