

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS3957  
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 11, 2016

Subject: 15757A – Safety Recall  
Under Hood Fire  
Revised Service Procedure section

Models: 1997-2004 Buick Regal  
2000-2004 Chevrolet Impala  
1998-1999 Chevrolet Lumina  
1998-2004 Chevrolet Monte Carlo  
1998-1999 Oldsmobile Intrigue  
1997-2004 Pontiac Grand Prix  
Equipped with 3.8L V6 engine (RPO L26, L32, L36 or L67)

To: All General Motors Dealers

The Service Procedure in this bulletin has been revised to provide service repair tips that may reduce the amount of time and effort required to perform the repair. In addition, beauty cover removal, retention, and disposal information is provided. Please discard all copies of bulletin 15757.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS