

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4294
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 13, 2016

Subject: 15757D – Safety Recall
Under Hood Fire
Revised Part Information, Service Procedure, and Warranty
Transaction Information sections

Models: 1997-2004 Buick Regal
2000-2004 Chevrolet Impala
1998-1999 Chevrolet Lumina
1998-2004 Chevrolet Monte Carlo
1998-1999 Oldsmobile Intrigue
1997-2004 Pontiac Grand Prix
Equipped with 3.8L V6 engine (RPO L26, L32, L36 or L67)

To: All General Motors Dealers

This bulletin is being revised to add specific, required sealant as an assembly aid to the Service Procedure, provide detailed repair information for proper application of sealant, and to adjust the Warranty Transaction Information section. Please discard all copies of bulletin 15757C.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS