



This Service Information bulletin supersedes SI 26 01 15 dated **November 2015**.

Changes to this revision are identified by a black bar.

## **SUBJECT**

### **Recall 15V-XXX – Checking Driveshaft Universal Joint**

## **MODEL**

F80 (M3 Sedan)  
F82 (M4 Coupe)  
F83 (M4 Convertible)

## **SITUATION**

BMW Group is conducting a Voluntary Safety Recall including Delivery Stop that involves F80, F82 and F83 vehicles produced from May 30, 2015 to October 11, 2015. These vehicles will require a Driveshaft Universal Joint inspection and possible replacement. There are a total of 42 vehicles affected by this Recall, with 34 that have been delivered to customers and eight in Center inventory. For your convenience, attached you will find the list of eight VINs that are affected by the Delivery Stop.

This bulletin will be updated with repair instructions and warranty information when it becomes available.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

**“A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. See Service Information Bulletin B26 01 15.”**