



MAZDA DEALER EMAIL

zoom-zoom

zoom-zoom

zoom-zoom

January 11, 2016

Attention: Mazda Service and Parts Managers

Subject: Safety Recall 9015L - Takata Passenger Air Bag Inflator

Safety Recall 9015L expands the affected vehicle population for Takata passenger air bag inflator to all 2003-2008 Mazda6 and all 2006-2007 Mazdaspeed6 vehicles nationwide. In addition, this recall also includes the following models:

- All Mazda6 and RX-8 vehicles not repaired under recalls 6913D and 7714F
- Mazda6 VINs not repaired under recall 8114L

SERVICE INFORMATION

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the passenger frontal air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger frontal air bag. An inflator rupture could result in metal fragments striking and potentially seriously injuring vehicle occupants. Dealers will replace the passenger air bag inflators of subject vehicles with a new one.

Owners of vehicles involved in 9015L will be notified by first class mail by mid-February.

Recall 9015L currently displays 'Not Launched' status in eMDCS for the newly added VINs, and 'OPEN' status for subject VINs that were not repaired under recalls 6913D, 7714F, and 8114L. After the Phase I owner notification letters are mailed in February, status will change to OPEN for VINs where the owners are notified of parts availability, and status for all other VINs will change to 'Preliminary Notification'.

- After a customer has been notified of parts availability, VIN inquiry on eMDCS will display 9015L OPEN.
- If a customer has not yet been notified of parts availability, VIN inquiry on eMDCS will display 9015L Preliminary Notification. If this customer requests the recall repair, please explain that they will receive a second notice by mail as soon as replacement parts are available for their vehicle.

Detailed parts and service information will be provided as soon as possible. Until final recall repair instructions are available, refer to the repair procedures in recall 8114L.

PARTS INFORMATION

Description	Part Number	Model	Quantity
Passenger Side Front Air Bag Inflator	GJYA-57-K80	Mazda6	1
Passenger Side Front Air Bag Inflator	FEY1-57-K80A	RX-8	1

A limited supply of replacement parts is available. A parts order screen for 9015L VINs in 'OPEN' status is now available. [Parts for 9015L are ordered to repair a specific VIN and are non-returnable.](#)

WARRANTY INFORMATION

	Replacement of Passenger Side Front Air Bag Inflator
	Mazda6, Mazdaspeed6, RX-8
Process Number	AF058A
Symptom Code	99
Damage Code	99
Causal Part Number	GJYA-57-K80 (Mazda6, Mazdaspeed6) FEY1-57-K80A (RX-8)
Quantity	1
Labor Operation Number	XXM12XRX
Labor Hours	0.4 hrs.

Please refer to the FAQs now available on eMDCS and MS3 for further information.

NOTE:

- Upon launch of 9015L, recalls 6913D and 7714F will be closed. Claims will be accepted under these recalls until Friday, January 15.
- Regional recall 8114L (HAH states only) will remain open only for the subject RX-8 and MPV vehicles.

We appreciate your support with this recall campaign.

Sincerely,

Mazda Technical Services