

[Next Unread Message](#)[View Message](#)

Sent on	01	08	2016	Expires on	01	29	2016
---------	----	----	------	------------	----	----	------

From	Motorcycle National Field Service
------	-----------------------------------

Subject	SAFETY RECALL: 2010-2016 VT750 Series, Service Bulletin Published
---------	---



Motorcycle National Field Service

January 8, 2016

**Service Bulletin: 2010-2016 VT750 Series - Bank Angle Sensor Replacement**

Dear Honda Powersports Dealer:

The Service Bulletin in support of the SAFETY RECALL of 2010-2016 VT750 series motorcycles for a defective bank angle sensor is posted on *IN*.

**SERVICE BULLETIN**

SAFETY RECALL: VT750 #6 includes the affected models, repair procedure, parts information, as well as warranty claim information.

Some models within the affected VIN range for this campaign were previously recalled to replace the bank angle sensor. This is a new recall for a different type of failure. Be sure to apply this recall repair to any units also affected by *S/B VT750C/C2B #5*.

**CUSTOMER NOTIFICATION**

AHM intends to mail customer letters mid-to-late January, based on vehicle registration information and regulatory agency approvals.

**PARTS INFORMATION**

Repair parts are available on open order.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine at (800) 421-1900, Option 9; through *TechLine Connect* on *IN*; or contact your District Service Manager.

Sincerely,

**American Honda Motor Co., Inc.**
**Bradley Little**

Manager, National Field Service

Motorcycle Division

Bulletin Number: 16-0006