

[Next Unread Message](#)[View Message](#)

Sent on	12	21	2015	Expires on	12	30	2015
From	Motorcycle National Field Service						
Subject	STOP SALE NOTICE; Safety Recall 2010-2016 VT750 Series						

STOP SALE NOTICE: 2010-2016 VT750 SERIES BANK ANGLE SENSOR REPLACEMENT

Dear Honda Powersports Dealer:

Honda is launching a Safety Recall of 2010-2016 model year VT750C/CA/CS, VT750C2/C2F/C2S, and VT750C2B motorcycles for a potentially defective bank angle sensor.

Honda has determined that engine vibration may cause the bank angle sensor's wiring to rub on a wire harness connector. Continuous vibration between the bank angle sensor wiring and the wire harness connector may create an open in the bank angle sensor electrical circuit. If an open in the bank angle sensor electrical circuit develops, the engine may stall while riding. An engine that stalls while riding increases the risk of a crash.

Some models within the affected VIN range were previously recalled to replace the bank angle sensor. This is a new recall for a different type of failure.

Effective immediately, YOU MUST NOT SELL any NEW or USED motorcycle affected by this recall, until it has been repaired according to the forthcoming Service Bulletin.

AFFECTED UNITS

Click the link the Service Bulletin link below to view the list of affected units.

NOTE: Your dealership will be violating Federal Law, violating your sales and service agreement, and risking chargeback of sales incentives if you sell any affected products prior to performing the inspection/repair procedure.

- To search for applicable recalls on a specific unit, use *Unit Information* on *iN*.
- To manage your affected inventory, use *eResponsibility Report*, effective Tuesday Dec 22, 2015

SERVICE BULLETIN The complete [Service Bulletin VT750 #5](#) will be published on or before January 8, 2016.

PARTS INFORMATION

Replacement parts will be available the first week of January, 2015.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine via TechLine Connect *iN*> *Service*> *TechLine Connect* or call (800) 421-1900, (Ext. 9) or your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.

Bradley Little
Manager, National Field Service
Motorcycle Division

Bulletin Number: 15-0363