

December 07, 2015

## IMPORTANT SAFETY RECALL

**This notice applies to your vehicle  
VINs are listed on the back of this page.**

Subject: Safety Recall 1015M Fontaine Ultra LT 5<sup>th</sup> Wheel  
NHTSA # 15V-641  
EXPIRATION DATE: NONE

1015M - 1US  
ARMELLINI EXPRESS LINES, INC.  
3446 SW ARMELLINI AVE  
PALM CITY, FL 34990

157764-1015M

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect, which relates to motor vehicle safety, exists in certain vehicles built with the Fontaine Ultra LT Fifth Wheel, manufactured between February 14, 2011 and December 5, 2012. The defect involves a susceptibility of the fifth wheel and its locking mechanism to cumulative damage that may cause the fifth wheel lock to function improperly or a failure of the locking mechanism to properly engage.

If the fifth wheel and locking mechanism are sufficiently damaged, the locking mechanism may fail to operate as intended and the trailer may unexpectedly detach from the tractor, increasing the risk of crash.

<b>The problem is...</b>	Damaged fifth wheel or locking mechanism on Fontaine Ultra LT Fifth Wheel
<b>Correction...</b>	Dealers will replace the fifth wheel top plate
<b>What you must do ...</b>	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to remedy the defect free of charge. Please contact a Peterbilt dealership to schedule this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at [www.Peterbilt.com](http://www.Peterbilt.com). This repair should take approximately 1.5 hours labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.


If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Doug Gunter  
Director of Warranty  
Peterbilt Motors Company

Our records indicate that these vehicles are affected by 1015M and are owned by:

**ARMELLINI EXPRESS LINES, INC.**

1XP4DP9X0CD157764  
1XP4DP9X2CD157765  
1XP4DP9X4DD195340  
1XP4DP9X6DD195341  
1XP4DP9X8DD195342  
1XP4DP9XXDD195343  
1XP4DP9X1DD195344  
1XP4DP9X3DD195345  
1XP4DP9X5DD195346  
1XP4DP9X7DD195347  
1XP4DP9X9DD195348  
1XP4DP9X0DD195349  
1XP4DP9X7DD195350  
1XP4DP9X9DD195351  
1XP4DP9X0DD195352  
1XP4DP9X2DD195353  
1XP4DP9X4DD195354  
1XP4DP9X6DD195355  
1XP4DP9X8DD195356  
1XP4DP9XXDD195357  
1XP4DP9X1DD195358  
1XP4DP9X3DD195359  
1XP4DP9XXDD195360  
1XP4DP9X1DD195361  
1XP4DP9X3DD195362  
1XP4DP9X5DD195363  
1XP4DP9X7DD195364  
1XP4DP9X9DD195365  
1XP4DP9X0DD195366  
1XP4DP9X9DD210706  
1XP4DP9X0DD210707  
1XP4DP9X2DD210708  
1XP4DP9X4DD210709  
1XP4DP9X0DD210710  
1XP4DP9X2DD210711  
1XP4DP9X4DD210712  
1XP4DP9X6DD210713

December 07, 2015

## IMPORTANT SAFETY RECALL

**This notice applies to your vehicle  
VINs are listed on the back of this page.**

Subject: Safety Recall 1015M Fontaine Ultra LT 5<sup>th</sup> Wheel  
NHTSA # 15V-641  
EXPIRATION DATE: NONE  
1015M - 38US

PACCAR LEASING CO.  
P.O. BOX 27634  
SALT LAKE CITY, UT 84127  
170701-1015M

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect, which relates to motor vehicle safety, exists in certain vehicles built with the Fontaine Ultra LT Fifth Wheel, manufactured between February 14, 2011 and December 5, 2012. The defect involves a susceptibility of the fifth wheel and its locking mechanism to cumulative damage that may cause the fifth wheel lock to function improperly or a failure of the locking mechanism to properly engage.

If the fifth wheel and locking mechanism are sufficiently damaged, the locking mechanism may fail to operate as intended and the trailer may unexpectedly detach from the tractor, increasing the risk of crash.

<b>The problem is...</b>	Damaged fifth wheel or locking mechanism on Fontaine Ultra LT Fifth Wheel
<b>Correction...</b>	Dealers will replace the fifth wheel top plate
<b>What you must do ...</b>	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to remedy the defect free of charge. Please contact a Peterbilt dealership to schedule this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at [www.Peterbilt.com](http://www.Peterbilt.com). This repair should take approximately 1.5 hours labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.


If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Doug Gunter  
Director of Warranty  
Peterbilt Motors Company

Our records indicate that these vehicles are affected by 1015M and are owned by:

**PACCAR LEASING CO.**

1XPBD49X9DD170701

December 07, 2015

## IMPORTANT SAFETY RECALL

**This notice applies to your vehicle  
VINs are listed on the back of this page.**

Subject: Safety Recall 1015M Fontaine Ultra LT 5<sup>th</sup> Wheel  
NHTSA # 15V-641  
EXPIRATION DATE: NONE  
1015M - 39US

MAY TRUCKING COMPANY  
4185 BROOKLAKE RD NE  
SALEM, OR 97303-9729

133465-1015M

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect, which relates to motor vehicle safety, exists in certain vehicles built with the Fontaine Ultra LT Fifth Wheel, manufactured between February 14, 2011 and December 5, 2012. The defect involves a susceptibility of the fifth wheel and its locking mechanism to cumulative damage that may cause the fifth wheel lock to function improperly or a failure of the locking mechanism to properly engage.

If the fifth wheel and locking mechanism are sufficiently damaged, the locking mechanism may fail to operate as intended and the trailer may unexpectedly detach from the tractor, increasing the risk of crash.

<b>The problem is...</b>	Damaged fifth wheel or locking mechanism on Fontaine Ultra LT Fifth Wheel
<b>Correction...</b>	Dealers will replace the fifth wheel top plate
<b>What you must do ...</b>	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to remedy the defect free of charge. Please contact a Peterbilt dealership to schedule this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at [www.Peterbilt.com](http://www.Peterbilt.com). This repair should take approximately 1.5 hours labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.


If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Doug Gunter  
Director of Warranty  
Peterbilt Motors Company

Our records indicate that these vehicles are affected by 1015M and are owned by:

**MAY TRUCKING COMPANY**

1XP4D49X4CD133465	1XP4D49X8CD133534	1XP4D49X7CD133606	1XP4D49X2DD134163
1XP4D49X6CD133466	1XP4D49XXCD133535	1XP4D49X9CD133607	1XP4D49X4DD134164
1XP4D49X8CD133467	1XP4D49X1CD133536	1XP4D49X0CD133608	1XP4D49X6DD134165
1XP4D49XXCD133468	1XP4D49X3CD133537	1XP4D49X2CD133609	1XP4D49X8DD134166
1XP4D49X1CD133469	1XP4D49X5CD133538	1XP4D49X9CD133610	1XP4D49XXDD134167
1XP4D49X8CD133470	1XP4D49X7CD133539	1XP4D49X0CD133611	1XP4D49X1DD134168
1XP4D49XXCD133471	1XP4D49X3CD133540	1XP4D49X2CD133612	1XP4D49X3DD134169
1XP4D49X1CD133472	1XP4D49X5CD133541	1XP4D49X4CD133613	1XP4D49XXDD134170
1XP4D49X3CD133473	1XP4D49X7CD133542	1XP4D49X6CD133614	1XP4D49X1DD134171
1XP4D49X5CD133474	1XP4D49X9CD133543	1XP4D49X8CD133615	1XP4D49X3DD134172
1XP4D49X7CD133475	1XP4D49X0CD133544	1XP4D49XXCD133616	1XP4D49X5DD134173
1XP4D49X9CD133476	1XP4D49X2CD133545	1XP4D49X1CD133617	1XP4D49X7DD134174
1XP4D49X0CD133477	1XP4D49X4CD133546	1XP4D49X3CD133618	1XP4D49X9DD134175
1XP4D49X2CD133478	1XP4D49X6CD133547	1XP4D49X5CD133619	1XP4D49XXDD134176
1XP4D49X4CD133479	1XP4D49X8CD133548	1XP4D49X1CD133620	1XP4D49X2DD134177
1XP4D49X0CD133480	1XP4D49XXCD133549	1XP4D49X3CD133621	1XP4D49X4DD134178
1XP4D49X2CD133481	1XP4D49X6CD133550	1XP4D49X5CD133622	1XP4D49X6DD134179
1XP4D49X4CD133482	1XP4D49X8CD133551	1XP4D49X7CD133623	1XP4D49X3DD134180
1XP4D49X6CD133483	1XP4D49XXCD133552	1XP4D49X9CD133624	1XP4D49X4DD134181
1XP4D49X8CD133484	1XP4D49X1CD133553	1XP4D49X0CD133625	1XP4D49X6DD134182
1XP4D49XXCD133485	1XP4D49X3CD133554	1XP4D49X2CD133626	1XP4D49X8DD134183
1XP4D49X1CD133486	1XP4D49X5CD133555	1XP4D49X4CD133627	1XP4D49XXDD134184
1XP4D49X3CD133487	1XP4D49X7CD133556	1XP4D49X6CD133628	1XP4D49X1DD134185
1XP4D49X5CD133488	1XP4D49X9CD133557	1XP4D49X8CD133629	1XP4D49X3DD134186
1XP4D49X7CD133489	1XP4D49X0CD133558	1XP4D49X4CD133630	1XP4D49X5DD134187
1XP4D49X3CD133490	1XP4D49X2CD133559	1XP4D49X6CD133631	1XP4D49X7DD134188
1XP4D49X5CD133491	1XP4D49X9CD133560	1XP4D49X8CD133632	1XP4D49X9DD134189
1XP4D49X7CD133492	1XP4D49X0CD133561	1XP4D49XXCD133633	1XPBD49X1DD184897
1XP4D49X9CD133493	1XP4D49X2CD133562	1XP4D49X1CD133634	
1XP4D49X0CD133494	1XP4D49X4CD133563	1XP4D49X3CD133635	
1XP4D49X2CD133495	1XP4D49X6CD133564	1XP4D49X5CD133636	
1XP4D49X4CD133496	1XP4D49X8CD133565	1XP4D49X7CD133637	
1XP4D49X6CD133497	1XP4D49XXCD133566	1XP4D49X9CD133638	
1XP4D49X8CD133498	1XP4D49X1CD133567	1XP4D49X0CD133639	
1XP4D49XXCD133499	1XP4D49X3CD133568	1XP4D49X7CD133640	
1XP4D49X2CD133500	1XP4D49X5CD133569	1XP4D49X9CD133641	
1XP4D49X4CD133501	1XP4D49X1CD133570	1XP4D49X0CD133642	
1XP4D49X6CD133502	1XP4D49X3CD133571	1XP4D49X2CD133643	
1XP4D49X8CD133503	1XP4D49X5CD133572	1XP4D49X4CD133644	
1XP4D49XXCD133504	1XP4D49X7CD133573	1XP4D49X6CD133645	
1XP4D49X1CD133505	1XP4D49X9CD133574	1XP4D49X8CD133646	
1XP4D49X3CD133506	1XP4D49X0CD133575	1XP4D49XXCD133647	
1XP4D49X5CD133507	1XP4D49X2CD133576	1XP4D49X1CD133648	
1XP4D49X7CD133508	1XP4D49X4CD133577	1XP4D49X3CD133649	
1XP4D49X9CD133509	1XP4D49X6CD133578	1XP4D49XXCD133650	
1XP4D49X5CD133510	1XP4D49X8CD133579	1XP4D49X1CD133651	
1XP4D49X7CD133511	1XP4D49X4CD133580	1XP4D49X3CD133652	
1XP4D49X9CD133512	1XP4D49X6CD133581	1XP4D49X5CD133653	
1XP4D49X0CD133513	1XP4D49X8CD133582	1XP4D49X7CD133654	
1XP4D49X2CD133514	1XP4D49XXCD133583	1XP4D49X9CD133655	
1XP4D49X4CD133515	1XP4D49X1CD133584	1XP4D49X0CD133656	
1XP4D49X6CD133516	1XP4D49X3CD133585	1XP4D49X2CD133657	
1XP4D49X8CD133517	1XP4D49X5CD133586	1XP4D49X4CD133658	
1XP4D49XXCD133518	1XP4D49X7CD133587	1XP4D49X6CD133659	
1XP4D49X1CD133519	1XP4D49X9CD133588	1XP4D49X2CD133660	
1XP4D49X3CD133520	1XP4D49X0CD133589	1XP4D49X4CD133661	
1XP4D49XXCD133521	1XP4D49X7CD133590	1XP4D49X6CD133662	
1XP4D49X1CD133522	1XP4D49X9CD133591	1XP4D49X8CD133663	
1XP4D49X3CD133523	1XP4D49X0CD133592	1XP4D49XXCD133664	
1XP4D49X5CD133524	1XP4D49X2CD133593	1XP4D49X4DD134150	
1XP4D49X7CD133525	1XP4D49X4CD133594	1XP4D49X6DD134151	
1XP4D49X9CD133526	1XP4D49X6CD133595	1XP4D49X8DD134152	
1XP4D49X0CD133527	1XP4D49X8CD133596	1XP4D49XXDD134153	
1XP4D49X2CD133528	1XP4D49XXCD133597	1XP4D49X1DD134154	
1XP4D49X4CD133529	1XP4D49X1CD133598	1XP4D49X3DD134155	
1XP4D49X0CD133530	1XP4D49X3CD133599	1XP4D49X5DD134156	
1XP4D49X2CD133531	1XP4D49X6CD133600	1XP4D49X7DD134157	
1XP4D49X4CD133532	1XP4D49X8CD133601	1XP4D49X9DD134158	
1XP4D49X6CD133533	1XP4D49XXCD133602	1XP4D49X0DD134159	
	1XP4D49X1CD133603	1XP4D49X7DD134160	
	1XP4D49X3CD133604	1XP4D49X9DD134161	
	1XP4D49X5CD133605	1XP4D49X0DD134162	