



SLINGSHOT
Slingshot Division
Polaris Industries Inc.
P.O. Box 47700
Medina, MN 55340-9960

IMPORTANT SAFETY RECALL
This notice applies to your vehicle
VIN: INSERT VIN HERE
Recall Campaign: 15V-777
Subject: 2015-2016 Slingshot
Headlight Jumper Harness Installation
PLEASE READ IMMEDIATELY

Dear Slingshot Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Slingshot Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2015 and 2016 Slingshot vehicles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

Polaris has determined that some Slingshot vehicles were manufactured with a headlight circuit that does not meet Polaris quality standards. In some vehicles, heat buildup in the engine compartment may cause the headlight circuit relay to derate below the required current draw of the headlights. In addition, temperatures produced at the fuse box terminal pin may be higher than desired. The result of such a condition could be a loss of forward lighting function. This could cause decreased visibility for the vehicle operator, increasing the risk of a vehicle crash.

What Polaris and your dealer will do:

Polaris will issue a *Safety Recall Bulletin* to all Slingshot dealers, with the appropriate instructions to install an auxiliary headlight jumper harness. Repairs will be made by an authorized Slingshot dealer at no cost to you. The actual repair should take under one hour to perform; however, it may take longer due to service scheduling requirements.

What you should do:

Contact your authorized Slingshot dealer to schedule an appointment to have the bulletin repairs performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Slingshot dealer.

If you have questions or if you need more information:

While your Slingshot dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, if you are having difficulty obtaining the recall repair outlined in this letter, or if you need assistance finding a Slingshot dealer, please visit the Slingshot web site at <http://www.polaris.com/en-us/slingshot> or contact our Slingshot Consumer Service Department by calling 1-855-863-2284.

This notice was mailed to you according to our most current registration information. If you no longer own your Slingshot vehicle, please contact your local Slingshot dealer to have the ownership information changed. The Slingshot Consumer Service Department cannot change ownership information without identification. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you have had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information regarding reimbursement please contact your Slingshot dealer or the Slingshot Consumer Service Department using the information above.

If you believe that the Slingshot Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to <http://www.safercar.gov>.

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Slingshot is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,

Polaris On-Road Vehicles