

April 10, 2014

ATTN: SERVICE MANAGER AND PARTS MANAGER

SUBJECT: R08 – 2015 UF 9 Speed Automatic Transmission Park System Failure

Please refer to instructions below from Customer Services Field Operations regarding Safety Recall Technical Advisory R08. Due to the incorrect inspection tool, all open orders for transmissions RL254810AL & RL248919AL will be cancelled. Please understand that these vehicles will need to be revalidated when the new inspection tool is received next week. The replacement transmissions will be available for order late next week, after the new inspection tools have been received at dealerships.



Updated 04/07/2015

Safety Recall Technical Advisory - R08 Transaxle Park Rod Inspection Tool

Safety Recall R08 was released to the dealers on 3/31/2015.

Most Park Rod Engagement Check Tools (special tool # 2023000210) were incorrectly built and shipped to dealers.

A Park Rod Engagement Check Tool rework kit has been developed to correct the inspection tool that was shipped to dealers.

Park Rod Engagement Check Tool rework kits will be shipped to the dealers the week of **4/13/2015**. Kits will contain the following parts which must be installed on the original tool in order to accurately inspect the transaxle park rod for engagement.

- Halfshell (Qty2)
- O-Ring (Qty 2)
- Park Rod Engagement Check Tool Pin with internal threads
- Rework Instructions Sheet

Please do not perform any more transaxle inspections until the inspection tool rework kit is received and the inspection tool is updated.

Contact Mopar Essential Tools – 1-855-298-2687 if there are any questions regarding receipt of the new inspection tool rework kit.

Thank You
Customer Services Field Operations
FCA US LLC

