



Patterson, James <jpatters@jaguarlandrover.com>

[LR US ALERTS] URGENT : SAFETY RECALL P068 RANGE ROVER RANGE ROVER SPORT VEHICLE DOOR MAY NOT LATCH and P065 LR4 PANORAMIC ROOF PANEL INCORRECT PRIMER

1 message

Irnapubs <lmapubs@jaguarlandrover.com>

17 June 2015 at 12:13

Reply-To: noreply@jaguarlandrover.com

To: 005m1brdxi@jlrdemo.netlink.com

Cc: UM-NSC-USA-LR-ALERTS <um-nsc-usa-lr-alerts@jaguarlandrover.com>

Please be advised that the system issue that was preventing the correct flagging in DDW of all cars affected by these 2 new safety recalls has now been resolved. All affected VIN can now be tracked in DDW as normal.

To assist with inventory checks please note the following:

P065 LR4 Glass Roof - Land Rover systems show zero unsold new cars are affected. All affected units have been sold.

P068 Range Rover and Range Rover Sport - The VIN range stated in the Service Bulletin includes a limited number of 16MY units that are all under JLRNA control. Selected VIN within the entire range are affected. The 15MY cut off VIN are as follows:

Range Rover end VIN FA223025

Range Rover Sport Line 1 end VIN FA524031 - units from this VIN up to FA599999 are unaffected.

Line 2 end VIN FA620146

The software fix required for P068 door latch is currently expected to be released Mid July. We will keep you informed on any changes to this plan as well as repair details for P065 panoramic roof glass when known.

We apologize for any inconvenience this may cause.

Please do not reply to this e-mail as responses cannot be monitored.



Jaguar Land Rover North America, LLC
555 MacArthur Boulevard
Mahwah, NJ 07430
JAGUARUSA.COM | LANDROVERUSA.COM