
January 30, 201501465 Version 1

Safety Recall: SRS Unit

AFFECTED VEHICLES

Year	Model	VIN Range
2003–04	Odyssey	Check the iN VIN status for eligibility

BACKGROUND

Electrical noise (interference) generated by the vehicle may inadvertently cause some or all of the vehicle's airbags to deploy. Many vehicles had an electrical noise suppressor installed under S/B 13-088, *Safety Recall: Electrical Noise May Cause Inadvertent Front Airbag Deployment*. In rare cases, even with the noise suppressor installed, some front airbags inadvertently deployed.

All vehicles will be recalled again to have a new SRS control unit installed.

If you have a vehicle eligible for S/B 13-088 arrive at your dealership, complete the repair by installing a noise suppressor. Once there are a sufficient number of SRS units available, this bulletin will be revised and customers will be notified to bring their vehicles back to a Honda dealership to replace the SRS unit.

This bulletin will be revised once repair procedure, parts information, and warranty claim information become available.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.