



RECALL CAMPAIGN BULLETIN

Reference:

NTB15-007

Date:

February 5, 2015

VOLUNTARY SAFETY RECALL CAMPAIGN 2009 GT-R STEERING COLUMN UPPER BEARING

CAMPAIGN ID #: R1502

APPLIED VEHICLES: 2009 GT-R (R35)

Check Service COMM to confirm campaign eligibility.

INTRODUCTION

Nissan is conducting a Voluntary Safety Recall Campaign on certain specific Model Year 2009 GT-R vehicles to replace the steering column assembly. This service will be performed at no charge for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number R1502 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service Comm for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

IMPORTANT: Follow all cautions, warnings, and notes in the Electronic Service Manual (ESM) when working on or near a Supplemental Restraint System (SRS), such as an air bag.

CAUTION: Handle interior trim carefully to avoid damage. Work with clean hands and clean tools to avoid dirt and stains. Use protective covers as needed.

1. Replace the steering column assembly.
 - Refer to the Electronic Service Manual (ESM), section ST-Steering System, for steering column removal and installation information.
 - Use the steering column assembly included in the steering column kit listed in the Parts Information.
 - Make sure to use the new bolts and nuts included with the steering column kit.
 - Reuse the upper joint.
 - After installation of the new steering column, “ADJUSTMENT OF STEERING ANGEL SENSOR NEUTRAL POSITION” is required, as described in the ESM.

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Steering Column Kit	D881B-KB61A	1
Kit Includes		
STEERING COLUMN (JOINT LESS)		1
BOLT-HEX,SPL WITH WASH		1
BOLT KEY LOCK UNIT		2
NUT STEERING WHEEL		1
NUT STEERING LWR JOINT		1
BOLT AIR BAG MODULE		2

CLAIMS INFORMATION

Submit a Campaign (CM) line claim using the following claims coding:

CAMPAIGN (CM) ID #	DESCRIPTION	OP CODE	FRT
R1502	Replace Steering Column Assembly	R15020	1.7 hrs.

