



Recall Campaign

Recall # 15V266 2015-200
HSM QUAD STEP RIVETS

Job Code: 9901242
Flate Rate: .5 per step

REQUIRES PARTS TO BE ORDERED FROM Jayco for every unit.

ACTION REQUIRED:

Inspect all steps to assure that a HSM product.
Determine the rivet configuration of the HSM step/s.
Repair per HSM procedures for specific configurations following HSM SRP 1502-0001

MODELS / UNITS:

2013 Seismic Fifth Wheel	3914	D19A	0131	2014 Seismic Fifth Wheel	3914	E19A	0051-0101
	3902	D19F	0051		3812	E19B	0051-0063
2015 Seismic Fifth Wheel	3914	F19A	0051-0085	2015 Seismic Fifth Wheel	3210	E19C	0051-0088
	3210	F19C	0051-0054		3712	E19D	0051-0068
	3712	F19D	0051-0056		3912	E19E	0051-0060
	3912	F19E	0051-0069		3902	E19F	0051-0077
	3902	F19F	0051-0063				
	4212	F19G	0051-0097				
2014 Pinnacle Fifth Wheel	36REQS	E1RB	0051-0146	2015 Pinnacle Fifth Wheel	36REQS	F1RB	0051-0157
	36RETS	E1RC	0051-0072		36KPTS	F1RG	0051-0147
	35LKTS	E1RE	0051-0069		36RSQS	F1RH	0050-0167
	36KPTS	E1RG	0051-0121		38FLFS	F1RJ	0051-0150
	36RSQS	E1RH	0051-0061		31RETS	F1RK	0050-0113
	38FLFS	E1RJ	0051-0181		36FBTS	F1RL	0050-0293
2014 Eagle Premier Fifth Wheel				2015 Eagle Premier Fifth Wheel	38FLSA	F1RM	0050-0268
	351MKTS	E1L8	0064		321RLTS	F1LF	0051-0072
	321RLTS	E1LF	0051-0120		331RETS	F1LG	0051-0140
	331RETS	E1LG	0050-0102		351RSTS	F1LH	0051-0118
	351RSTS	E1LH	0050-0110		371FLFS	F1LJ	0051-0146
	371FLFS	E1LJ	0050-0122		331RKTS	F1LK	0050-0082
	351RLTS	E1LM	0051-0124		351RLTS	F1LM	0051-0082
	351MKTS	E1LU	0051-0109		351MKTS	F1LU	0051-0080
	343RKJS	E1LW	0051-0083		361REQS	F1LX	0051-0164
	361REQS	E1LX	0051-0231		375BHFS	F1LY	0051-0356
	375BHFS	E1LY	0050-0270				

Parts Kit

Note: Kit can only be ordered using the order form included with this bulletin.

Please refer to HSM Service Repair Procedure 1502-001 Page 4 for contents.

Tools Required

Please refer to HSM Service Repair Procedure 1502-0001 Page 4 for listing.