



SUBJECT

Delivery Stop: Side Impact Performance

MODEL

F56 (Cooper Hardtop 2-door)

SITUATION

A Delivery Stop has been issued on certain F56 Cooper models produced from December 2013 to March 2015.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected.

AFFECTED VEHICLES

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Inquiry or ISPA Light with the description:

- Defect Code 00 51 61 03 00, Delivery Stop, Side Impact Performance M51 04 15

PROCEDURE

This Service Information will be updated later this week.

Refer to the attachments.