

Thor Motor Coach Recall Repair Instructions



Recall # 15V-530
Description/Title: **Axis-Vegas Heather Control Vent Selection**

Affected Product Line(s): **Certain 2016 Axis and Vegas Motorhomes**

Service Campaign # : **RC000103** Released Date: **8/27/2015**

Failure Code: **TMCRC80440N** Document Date: **8/27/2015**

Time Allowed: **0.5** Document Revision: **A**

Items needed: 1 ea Jumper Harness TMC Item Number 0338838

UNITS AFFECTED: Certain Axis and Vegas motorhomes. See Affected list at the end of the repair instructions.

DIRECTIONS:

Remove cover located above the Instrument cluster.



Using a Flat head screwdriver turn each screw counter clockwise.



The spring loaded screws will pop up.



Remove cover by lifting up on the screws and pulling toward windshield.




Locate 2-position connector (will have a 10 ga red and 14 ga red wire).



This is the Jumper you should have.



Disconnect by pressing the tabs on each side of the plug and pull apart.



Install Jumper into mating connectors. Color to color



After the Jumper is installed. Re-assemble the dash.

